Weathertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/10010MC-2723/1

Work Order Type: Weatherization

Audit Name: 10010MC-2723

CLIENT INFORMATION

Client Name: Address:

Client ID: 10010MC-2723 LEBANON, TN 37087

Alt. Client ID: WILSON

<u>AGENCY INFORMATION</u>

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Address: (PO Box 310) 233 Legends Drive **Fax:** (615) 742-3911

Lebanon, TN 37088 Email Address:

Agency Contact: ROBINETTE, A. K. Work Phone:

Cell Phone: (615) 476-8766

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

AUDITOR: A.K. ROBINETTE 615.476.8766 SITE BUILT IN 1950 TYPE: BRICK SF:816

ALL WORK TO COMPLY WITH TWFG.

CONTRACTOR TO FOLLOW APPLICABLE CITY (OR COUNTY) DEPARTMENT OF CODES AND BUILDING SAFETY REQUIREMENTS; 2009 INTERNATIONAL RESIDENTIAL CODE WITH LOCAL AMENDMENT, INCLUDING ISSUANCE OF PERMITS AND INSPECTIONS AND 2009 IECC.

CERTIFIED FIRM/RENOVATOR REQUIRED.

Client Name:
Client ID: 10010MC-2723
Alt. Client ID: WILSON

Work Order (Bid Form)

Work Order Name: WO/10010MC-2723/1 Report Run On: 10/10/2011 DOE Weatherization Assistant Version 8.6.0

Page 1 of 7

Pre-a Targ mea: 1 Se 2. Pe door 3. re	glaze windows stall light switch and recep	ite to be reconstruction owing air sense. Sound the interest in the sense.	duced teals. Perior a				s	
swee 6. Lid Top Liqui retur	eatherize exterior doors, in eps. quid white Mastic to be apported by of boot where it meets sub d Mastic to be applied to in n box where it meets retur	ncluding cau olied to enti ofloor to be onside of retu n register w	ulking, re insic caulkeo urn to s vith app	weatherstrip de of boot to d with appro seal all seam propriate cau	seal all s priate ca is. Seal ilk.	or seams. ulk.		
111710	idition Contractor made rep	nace parte t		Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
⁰ Miscellaneous	Su Infiltration Reduction	Each	1					
Other Detail								
			Measur	- O. t. T. 4-1]	_	

Measure 2	User-Spec	Ceiling R
-----------	-----------	-----------

Components A1

Ir	spec	te

Comment ATTIC BLOWN CELLULOSE. Install approx R-29 to improve total attic insulation to a total of a R-38.

Insulate approx. 816 SF of Attic with Blown Cellulose.

Includes labor cost. Contractor to install 1 ruler for every 300 SF of attic space showing depth of insulation. Build insulation dam around attic access and insulate per twfg. Insulate attic hatch to r-30 and weatherstrip to seal. Hatch must have locking device. Install baffles and dams to prevent loose fill insulation from entering soffitt and covering vent. Seal all holes, gaps and penetrations in attic before insulating, including boxes/dams and all b-vent pipe. Seal around chimney with sheet metal and high temperature silicone or fire resistant foam and install dam around chimney. Contractor to install using Resnet Grade 1 Standards.

Contractor's note: A. 2 attic access's one 19x23 and one 24 x 36

B. App. 3 inches of existing insulation, add additional r-29

for a total of r-38

at completion of job.

				Estimated			Actual		
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
Insulation	Attic Insulation - Blown Cellulose - R-29	SqFt	816						
2 Labor	Attic Insulation - Blown Cellulose - R-29	SqFt	816						
Miscellaneous Su	Air sealing attic/ inc attic access	Each	2						
Other Detail			1			1			
			Measur	e Sub Total:		;	Sub Total:		
Field Notes:									

Measure 3 Li	ghting Retrofits			Componen	ts LT1,L	T2,LT3	, I	Inspected
Comment								
				Estimated	<u> </u>			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact FI 13 Watt	Each Lamp	3					
2 Labor	Compact Fl 13 Watt	Each Lamp	3					
3 Lighting	Compact Fl 13 Watt	Each Lamp	3					
4 Labor	Compact Fl 13 Watt	Each Lamp	3					
5 Lighting	Compact Fl 13 Watt	Each Lamp	3					
6 Labor	Compact Fl 13 Watt	Each Lamp	3					
Other Detail								
			Measur	re Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 10/10/2011

Measure 4 DW	H Tank Insulation	on <i>Components</i>					Inspecte	
Insulate	ATER TANK to TWFG steen to the steen tank with a miss satisfies a miss satisfies and the steen tables. It is not satisfies to the steen the steen tables and the steen tables are satisfies as the steen tables are steen to the steen tables are steen tables as the steen tables are steen tables. The steen tables are steen tables.		r-8 insı	ulation				
					Actual			
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equip	DHW Tank Insulation	Each	1					
Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes: Measure 5 DW	H Pipe Insulation			Componen	nts		,	Inspecte
Measure 5 DW Comment HOT W	H Pipe Insulation ATER PIPE INSULATION e approx. the first 6 ft. of vectors of the country of t		VFG st	andards. udes labor o	cost. All	corners	i	Inspecte
Measure 5 DW Comment HOT W Insulate must be	ATER PIPE INSULATION approx. the first 6 ft. of vector properly.		VFG st s. Incl	andards. udes labor d Estimated	cost. All		Actual	Inspecte
Measure 5 DW Comment HOT W	ATER PIPE INSULATION approx. the first 6 ft. of v	water pipe	VFG st	andards. udes labor o	cost. All	corners Qty	i	
Measure 5 DW Comment HOT W Insulate must be	ATER PIPE INSULATION approx. the first 6 ft. of vecut properly. Description / Comment	water pipe <i>Units</i>	VFG st s. Incl	andards. udes labor d Estimated	cost. All		Actual	
Measure 5 DW Comment HOT W Insulate must be Material / Labor Insulation Labor	ATER PIPE INSULATION e approx. the first 6 ft. of vecut properly. Description / Comment DHW Pipe Insulation	water pipe <i>Units</i> Each	VFG st s. Incl Qty 1	andards. udes labor d Estimated	cost. All		Actual	
Measure 5 DW Comment HOT W Insulate must be Material / Labor Insulation Labor	ATER PIPE INSULATION e approx. the first 6 ft. of vecut properly. Description / Comment DHW Pipe Insulation	water pipe <i>Units</i> Each	VFG st s. Incl Qty 1	andards. udes labor d Estimated	cost. All		Actual	
Measure 5 DW Comment HOT W Insulate must be Material / Labor Insulation	ATER PIPE INSULATION e approx. the first 6 ft. of vecut properly. Description / Comment DHW Pipe Insulation	water pipe <i>Units</i> Each	VFG st s. Incl Qty 1	andards. udes labor d Estimated	cost. All		Actual	Total

Report Run On: 10/10/2011

Measure 6 CO N	Nonitor is Needed			Componen	ts			Inspecte
Comment Install 1	CO MONITORS							
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	Carbon Monoxide Detector w/ lithium battery	Each	1					
Labor	labor		1					
Other Detail						,		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes: Measure 7 Prac	tice Lead Safe Weathe	rization		Componen	ts			Inspecte
<i>Measur</i> e 7 Prac (Wall			atheriz	Componen ation	ts			Inspecte
Measure 7 Prac (Wall	ls)		atheriz	-			Actual	Inspecte
<i>Measure</i> 7 Prac (Wall <i>Comment</i> House b	ls)		atheriz Qty	ation		Qty		Inspected
<i>Measure</i> 7 Prac (Wall <i>Comment</i> House b	uilt in 1950/ practice lea	nd safe we		ation <i>Estimated</i>	·	Qty	Actual	
Measure 7 Prac (Wall Comment House b	uilt in 1950/ practice lea	nd safe we	Qty	ation <i>Estimated</i>	·	Qty	Actual	
Measure 7 Prac (Wall Comment House b # Material / Labor Health and Safety	uilt in 1950/ practice lea	nd safe we	Qty	ation <i>Estimated</i>	·	Qty	Actual	
Measure 7 Prac (Wall Comment House b # Material / Labor Health and Safety	uilt in 1950/ practice lea	nd safe we	Qty	ation <i>Estimated</i>	·	Qty	Actual	
Measure 7 Prac (Wall Comment House b # Material / Labor Health and Safety	uilt in 1950/ practice lea	Units Each	Qty 1	ation <i>Estimated</i>	·		Actual	
Measure 7 Prac (Wall Comment House b # Material / Labor Health and Safety	uilt in 1950/ practice lea	Units Each	Qty 1	ation Estimated Unit Cost	·		Actual Unit Cost	
Measure 7 Prac (Wall Comment House b # Material / Labor Health and Safety Other Detail	uilt in 1950/ practice lea	Units Each	Qty 1	ation Estimated Unit Cost	·		Actual Unit Cost	

Report Run On: 10/10/2011

measure o Sinc	ke Detector is Needed			Componen	ເວ			mopeoice
	DETECTORS total of 2 smoke detector detector must have tamp					nard-		
				Estimated	I		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor	labor		2					
Health and Safety	Smoke alarm w/ tamper resistant lithium battery	Each	2					
Other Detail			1	1		1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	rder Gra	nd Total:		Gran	d Total:	